

SECTION 1
SCALE: 3/4" = 1'-0"



TYPICAL FASTENING FOR FLAT FLOOR TRUSS @ SINGLE WALL BEARING CONDITION

SECTION 2
SCALE: 3/4" = 1'-0"



SECTION 3
SCALE: 3/4" = 1'-0"



SECTION 4
SCALE: 3/4" = 1'-0"



SECTION 5
SCALE: 3/4" = 1'-0"



SECTION 6
SCALE: 3/4" = 1'-0"



SECTION 7
SCALE: 3/4" = 1'-0"



SECTION 8
SCALE: 3/4" = 1'-0"



SECTION 9
SCALE: 3/4" = 1'-0"



These A Bolts were no poured into the bond beam. Is there an adhesive anchor equivalent?

SECTION 10
SCALE: 3/4" = 1'-0"



SECTION 11
SCALE: 3/4" = 1'-0"



SECTION 12
SCALE: 3/4" = 1'-0"



SECTION 13
SCALE: 3/4" = 1'-0"



SECTION 14
SCALE: 3/4" = 1'-0"



SECTION 15
SCALE: 3/4" = 1'-0"



SECTION 16
SCALE: 3/4" = 1'-0"



SECTION 17
SCALE: 3/4" = 1'-0"



SECTION 18
SCALE: 3/4" = 1'-0"



SECTION 19
SCALE: 3/4" = 1'-0"



SECTION 20
SCALE: 3/4" = 1'-0"



SECTION 21
SCALE: 3/4" = 1'-0"



SECTION 22
SCALE: 3/4" = 1'-0"



SECTION 23
SCALE: 3/4" = 1'-0"

Thorson Baker + Associates
CONSULTING ENGINEERS
3030 West Streetsboro Road (330) 659-6688 Ph.
Richfield, Ohio 44286 (330) 659-6675 Fax

mota design
2321 Second Street
Suite 102
Cuyahoga Falls, Ohio
P. 234.738.2840
F. 330.947.3009
www.MotaDesignGroup.com

TESTA COMPANIES

Villa San Bernardo Motherhouse

Villa San Bernardo LLC
1160 Broadway Avenue
Bedford OH, 44146

Issue: PERMIT & BID SET
Date: 02/02/2017
Project Number: 14-063

No.	Description	Date
1	BLDG DEPT COMMENTS	01/27/2017

FLOOR SECTIONS

Sheet Number:
S3.2

Copyright © 2016 Mota Design Group