

**Key**

- 1 fastener
- 2 steel plate

- a) Fastenings without hole clearance for all edge distances and for all load directions, and fastenings with hole clearance according to Table 6.1 situated far from edges ( $c_i \geq \max\{10h_{ef}; 60d_{nom}\}$ ) for all load directions and fastenings with hole clearance according to Table 6.1 situated near to an edge ( $c_i < \max\{10h_{ef}; 60d_{nom}\}$ ) loaded in tension only
- b) Fastenings with hole clearance according to Table 6.1 situated near to an edge ( $c_i < \max\{10h_{ef}; 60d_{nom}\}$ ) for all load directions