


CRAWL SPACE



1 TOP OF WALL
 1 1/2" = 1'-0"

07/09/24
19.052

Meadow Brook Villas Building C
Integrity Structures

ACS 17
